

# UNIVERSAL DIGITAL PROTRACTORS


## OPERATION AND CARE MANUAL

To take full advantage of Universal digital protractors, read this manual thoroughly before using it. After reading, retain this manual for future reference. Specifications of Universal digital protractors and the information in this manual are subject to change without notice.



### Product Features

- P Made of stainless steel throughout
- P Measuring Range: 360°, Resolutions: 30"/0.008°
- All measuring faces is finished
- With fine-adjustment
- With acute angle attachment

### Nomenclature



### ⚠ Caution



### ⚠ Important

- Any excessive shock should avoided.
- Do not disassemble or modify the instrument.
- Before using this instrument for the first time, wipe the rust preventive oil from the instrument with a soft cloth.
- Please take rust preventive oil, if do not use for a long time.

## BUTTON USAGE

### 1. PRESET button:

- a) Short pressing this button, entering set mode:
- b) Long pressing this button, can set Pre-value.
- c) After finish setting, short press "ZERO" button to exit setting mode, the LCD display degree what is setting value.

### 2, MODE button

Short pressing this button, you can choice 0-90" ,0-180" and 0-360° ,meantime LCD will display



### 3, +/- button:

Short pressing this button, can change direction of display(When the LCD display 360" 00' 00", after short pressing this button, the LCD will display 000" 00' 00" ).

### 4, /ZERO/ON button:

- a) Short pressing this button, can zeroset at any degrees or power on.



















## Specification

---

Measuring range	0-360°
Resolution	30"/ 0.008 °
Accuracy	± 5'
Material	Stainless steel throughout
The blade	150mm, 300mm,200mm blade for selected

---

## How to using



## BUTTON USAGE

### 1、 PRESET button:

- a) Short pressing this button, entering set mode;
- b) Long pressing this button, can set Pre-value.
- c) After finish setting, short press "ZERO" button to exit setting mode, the LCD display degree what is setting value.

### 2, MODE button

Short pressing this button, you can choice 0-90" ,0-180" and 0-360" ,meantime LCD will display



### 3, +/- button:

Short pressing this button, can change direction of display(When the LCD display 360" 00' 00", after short pressing this button, the LCD will display 000" 00' 00" ).

### 4, /ZERO/ON button:

- a) Short pressing this button, can zeroset at any degrees or power on.

## Specification

Measuring range	0-360°
Resolution	30"/ 0.008 °
Accuracy	± 5'
Material	Stainless steel throughout
The blade	150mm, 300mm,200mm blade for selected